ACE2 SOFTWARE RELEASE HISTORY

General

Minimum recommended software version: 1.6.3

Software update methods:

- **Local update:** CATVisor Commander 2.9 or later, service port connection with USB cable. Typical update time 1 min.
  File: ACE2_appl_x-x-x.srec
- **RIS mode remote update:** Unicast or broadcast update with SmartLoader. Contact Teleste support for details on software update via RIS.
  File: ACE2_appl_x-x-x.srec

LATEST VERSION

Version 1.7.100, released 17.2.2025 – Minor USB fix

Compatibility

Compatible with all ACE2 hardware versions.

All required viewer files are included in DUS100 package version 5.1 or later.

Fixes

- Fixed: USB port can occasionally hang up, requiring a SW/HW reset to recover operation. This can occur e.g. if the AC6902 BT dongle connects/disconnects multiple times in succession. (case 1825, 1837)

OLDER VERSIONS

Version 1.7.1, released 17.4.2018 – Enhancements and minor bug fixes

Compatibility

Compatible with all ACE2 hardware versions.

Note that diplexer 1/2 selection is maintained when software is updated from 1.6.3 to 1.7.1 but not maintained if software is updated back to 1.6.3.

Enhancements

- Added support for using CXF065 diplexer also in “diplexer 2” slots. (Shout 34648, 34749, 34752)
- Changed RIS functionality: Added “Locked” status, indicated with blinking green “RIS” led, where packets are received OK but no packets are addressed to this unit. This usually means that device is not on HDM155 RIS controller’s device list. (Shout 31367, 33630)

Fixes

- Internal changes not visible to the end user. (Shout 28030, 30002, 31669, 31702, 32638, 32664, 32716, 32760, 32788, 32793, 32822, 32840, 32859, 32881, 32894, 32896, 32904, 32910, 32922, 33016, 33110, 33184, 33225, 33294, 33559, 33588, 33599, 33605, 33616, 33670, 33729, 33739, 34139)

Version 1.6.3, released 14.6.2017 – First customer release

Compatibility

Compatible with all ACE2 hardware versions.